Name of Work: Estimate for Providing Missing Covering Slabs at KNV 2nd Stage,Kempanna Layout, Venkatagiriyappa in Ward no 10,(Doddabommasanda),Vidyaranyaoura Sub Division

GPS Map Camera
Bengaluru, KA, India
2nd Cross Road, Vidyaranyapura, Bengaluru, 560097, KA, India
Lat 13°3'47"N, Long 77°33'27"E
10/07/2021 01:53 PM

Smitha. N L
AEW10

AEE (VRP) BD

Name of Work: Estimate for Providing Missing Covering Slabs at KNV 2nd Stage,Kempanna Layout, Venkatagiriyappa in Ward no 10,(Doddabommasanda),Vidyaranyaoura Sub Division



Suvetha. N K
AGW10

AEE (VRP) SD

Name of Work: Estimate for Providing Missing Covering Slabs at KNV 2nd Stage,Kempanna Layout, Venkatagiriyappa in Ward no 10,(Doddabommasanda),Vidyaranyaoura Sub Division

Smitha .N.L
AE W10

AEE (VRP) SD